BUILDING SAFETY CERTIFICATE

No. 178

Dated: 01.04.2024

It is certified that the existing building Montessori Public School at Jhungian Road, Near IDBI Bank, Kharar is having block(s)/Floors) as per details below:

Details of Block(s) in School	Block (1)	Block (2)	Block (3)
No. of Floor(s)in the Block	4		

The building is owned/occupied by Montessori Public School, Kharar have complied with the Building safety requirements as per visual inspection and verified by Mr. Munish Bansal, Asistant Engineer of Public Works Department on 01.04.2024 in the presence of Amitoj Grewal, Principal Montessori Public School, Kharar and that the building/premises is fit for occupancy for running school with effect from 01.04.2024 for a period of 1 year in accordance with rule and subject to compliance of the specific conditions as appended.

- 1. The internal structural stability of school building cannot be checked from its external appearance. So, if at any time there is any damage to the building then the school authority itself will be responsible for it.
- 2. If any additions/alterations and modifications are made to the building by the school authority, it should be done under the supervision of a technically qualified engineer and a certificate should be obtained from that engineer that the building will be structurally safe by doing this addition/alteration and modification and after doing this work, the school should again get a school building safety certificate.
- 3. If the building is damaged by flood and there is any settlement in Walls/Foundation and sagging in the roof then the school authority will immediately bring this to the notice of the department.

4. If Fire Certificate is not renewed before the completion of the building safety certificate, this certificate will be considered null and void.

Issued on **01.04.2024** at Mohali by

Sub Divisional Engineer Construction Sub-Division No.2 PWD B& R S.A.S. Nagar

> Sub Divisional Engineer, Constn. Sub Divn. No. 2 PWD B&R, SAS Nagar.